

<b>Notification #:</b>	20080828	<b>Revision:</b>	1.0	<b>Page:</b>	1 of 2
<b>Release Date:</b>	August 28, 2008				
<b>Notification Status:</b>	Advisory <input type="checkbox"/>	Mandatory <input type="checkbox"/>	Announcement <input checked="" type="checkbox"/>		
<b>Classification:</b>	Firmware <input type="checkbox"/>	Hardware <input checked="" type="checkbox"/>	Policy/Procedure <input type="checkbox"/>		
<b>Hardware:</b>	TAIKO - 8MBit				
<b>Description:</b>	PUB-7				
<b>Interface:</b>	ID-002/003/0D3/0E3				
<b>Firmware version(s):</b>	N.A.				
<b>Checksum (CRC):</b>	N.A.				

## Conditions

The specification of Hardware modification for TAIKO in JCM-Germany.

The CPU board has been changed in the past. Below you can find the information concerning. The replacement has been made because the PIN OUT of 10 pin connector was not correct.



Blue JCM Logo on the old and new TOP COVER of Taiko with an old and new board. Old board on the right side and new Board on the left side.

Please find on the picture above the old CPU board on the left and the new CPU board on the right side. The old board has white letters and the new one has yellow letters.

On the old board you can see an additional harness at PIN OUT connector (with Label “DO NOT REMOVE”).

This cable has been added to correct the wrong PIN OUT.

The old board (left) must be used with an external harness named “DO NOT REMOVE” that was supported by Japan Cash Machine with every TAIKO Bill Validator.

## Customer Notification

The new board (right) does not need an external harness, due to the PIN OUT is correct.

Taiko with an old board inside was offered with two different labels on the TOP COVER.



A black JCM Logo on the older Top Cover.

### **ACTION needed**

If you receive a CPU board as a spare part with the EDP No. #137778, does not matter if the TOP COVER is black or blue, the external harness must be removed.

**Reason:**

The CPU Board has already the correct PIN OUT. This cable is not needed any more.

The Pin Out is described in the current TAIKO manual.

**For any additional information about specification changes JCM is requesting to contact your local distributor or supplier!**